Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 10/16/2012, 10/17/2012, 10/18/2012, 10/19/2012	Man Days: 4
Inspection Unit: Springfield	
Location of Audit: Springfield	
Exit Meeting Contact: Mark Mancewicz	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Charles Gribbins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION			
Location of Construction:	Construction Performed By:		
Pine Creek & Lake Mere Drive Springfield, Illinois		Ameren Illinois Crew from Lincoln Service Area	
Contractor Foreman:	This was an A	This was an Ameren Crew	
Operator Inspector:	An inspector v	An inspector was not present on the job site.	
	Pers	son(s) On Job Site	
Mike Martinie			

#### Description of Construction:

The scope of the construction site at Pine Creek and Mere Drive consisted of the installation of new plastic main for a new subdivision being built.

MAIN INSTALLATION		Status
192.55	Steel	No
192.59	PE	Yes
192.59	Other	No
192.5	Class location :	Class 3
192.619,192.621,192.623	MAOP	60#
192.63	Pipe Size :	2"

192.55,192.59	Specification:	ASTM D2513
192.55,192.59	Manufacturer :	Driscoplex
192.55,192.59	Pipe Grade :	PE 2406/2708
192.55,192.59	Wall Thickness :	DR 11.0
192.63(a)(2)	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
General Comment:		
Staff reviewed the markings on the pipe and included t 2" IPS DR 11.0 Driscoplex 6500 Gas PE 2406/2708 CI	hose marking in the report. EE Astm D 2513 KV 314 NSF Gas U.P. Code 01-08-12.	
192.227	Date of Welder qualification:	Not Applicable
General Comment:		
Welding activities were not conducted as part of this co	onstruction.	
192.227	Welder's Name:	Not Applicable
General Comment:		
Welding activities were not conducted as part of this co	onstruction.	
192.225,192.275,192.277,192.279,192.283	Is pipe joined in accordance with approved written procedures?	Satisfactory
General Comment:		
Staff was present at the construction site joining activit	ies were not being performed at the time of this inspection.	
192.285	Date of Plastic Joining Qualification :	Not Checked
General Comment:		
Staff was present at the construction site; no joining ac	tivities were being performed.	
192.285	Joiner's name:	Not Checked
General Comment:		
Staff was present at the construction site; no joining ac	tivities were being performed.	
192.455	Is buried metallic pipe coated?	Not Applicable
General Comment:		
Steel pipe was not being used at this construction site.		
192.461	Does coating meet 192.461?	Not Applicable
General Comment:		
Steel pipe was not being used at this construction site.		
192.455(a)(1)	Is cathodic protection being provided?	Not Applicable
General Comment:		
Steel pipe was not being used at this construction site.		

192.455(a)(1)	Is cathodic protection being provided? By Anodes:	Not Applicable
General Comment:		
Steel pipe was not being used at this constructio	n site.	
192.455(a)(1)	Is cathodic protection being provided? By Rectifier:	Not Applicable
General Comment:		
Steel pipe was not being used at this constructio	n site.	
192.461(c)	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:		
Steel pipe was not being used at this construction	n site.	
192.467	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
Steel pipe was not being used at this construction	n site.	
192.479	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		
Staff did not inspect any above ground facilities t	there were none present at this job site main installation only at this time.	
192.303	Are comprehensive written construction specifications available and adhered to?	Satisfactory
General Comment:		
Staff reviewed the procedures and observed that	t installation of the plastic main.	
192.305	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
General Comment:		
Ameren has quality assessors the review and ob	serve the employees to insure construction specifications are being adhered to.	
192.307	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	Satisfactory
General Comment:		
Staff was not no site when the operator performed did state that they did not find any damages that	ed the visual inspection of there materials. Staff however did inquire about the inspection would impair its serviceability.	of material; the operator
192.319	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Not Checked
General Comment:		
Staff did not observe the backfilling at this jog site	е.	
192.321(c)	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory

General Comment:		
The pipe at this location was hand laid into an c	ppen cut trench.	
192.321(e)	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
Staff noted that the tracer wire was laid into the	trench as the pipe was being lowered into the trench.	
192.325	Are required clearances from underground structures being maintained?	Satisfactory
General Comment:		
At this location several measurements were tak	en the depth of the pipe was 34" form the top of the pipe after laying it in the trench.	
192.327	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
General Comment:		
The distribution main was being installed in a cl main must be installed with at least 24 inches (t	ass three location with a depth of 34" (b) Except as provided in paragraphs (c) and (d) of 610 millimeters) of cover.	this section, each buried
192.503	Are general testing requirements being met?	Not Checked
General Comment:		
Staff was not onsite when the operator perform	ed the pressure test.	
192.517	Are records being made of strength and leak tests?	Not Checked
General Comment:		
Staff was not onsite when the operator preform	ed the pressure test or filled out the records for the pressure test.	
192.807	Were covered employees Operator Qualification records reviewed to ensure qualification?	Not Applicable
General Comment:		
At the time of inspection staff did not review ope	erator qualifications.	
192.805(c)	Were non-qualified personnel being "directed and observed" by a qualified individual?	Not Applicable
General Comment:		
There were not any non qualified personnel on	the job site.	
192.805(c)	Were span of control limitations being followed?	Not Applicable
General Comment:		
There were not any non qualified personnel on	the job site.	
Was a Protocol 9 (Form 15) Complete	d?	No
General Comment:		

Staff did not complete a form 15 operator qu	ualification protocol inspection.	
192.614	Were One Call Notifications performed as required?	Satisfactory
General Comment:		<u>.</u>
Staff observed locating marks at the job site	and reviewed the JULIE dig ticket #A283149.	
192.614	Dig Ticket #	JULIE number A283149